

Review of Redside Dace Habitat Corridor Realignment: Morphology, Sedimentology and Habitat Suitability within Aged Natural Corridor Designs


Paul Villard¹, Mark Heaton²

¹GEO Morphix Ltd., Milton, Canada

²Ontario Ministry of Natural Resources and Forestry

5th International Conference on Natural Channel Systems

September 26-27, 2016, Niagara Falls, Ontario



Outline


- Natural Channel Design, Corridor Re-alignment, and Redside Dace Habitat
- Detailed Observations on Four Realigned Channels/Corridors
 - Habitat/Geomorphological Observations
 - Ecological Summary
- Conclusions
- Lessons Learned



Redside Dace (*Clinostomus elongatus*)


- Status: Endangered, listed in 2009
- Habitat is protected under law by MNRF
- Habitat threats: habitat loss due to urban and agricultural development






Preferred Habitat Characteristics

- Morphological elements
 - Deep pools (resident habitat / overwinter) and shallow riffles (spawning, oxygenation)
 - Banks: undercut with submerged branches and logs
 - Low velocity zones - near zero
 - Gravels for spawning
- Riparian elements
 - ***Open meadow*** surroundings with overhanging vegetation
 - Enhance infiltration through design elements
 - Remove barriers (e.g., dams, weirs)





Why These Corridors?

- Four channels selected on basis of:
 - Known opportunity for Redside Dace occupancy
 - Older NCD channels showing > 10 years of evolution
 - Historical /ongoing monitoring completed – from at least four site – data for comparison
 - All the projects included full reconstruction of the corridors
 - All have similar bankfull channel configurations
 - All had limited deep pools reducing opportunity for overwintering
 - Design by a range of practitioners reducing a myopic review

Overview of Work Completed

- Surveys completed:
- Rapid assessments including:
 - sketch maps,
 - channel geometry,
 - velocity, and
 - substrate characteristics

- Sub-reach sketch maps – inventory habitat elements as well as mapping out sedimentology and morphological conditions within watercourse
- Drone Surveys – georeferenced aerial photos of site – review planform and riparian zone
- Late Summer Fish Surveys



General Site Characteristics		Project Code:
Date:	Aug 28, 2016	Stream/Reach:
Weather:		Location:
Field Staff:	FF/LS/AT	Watershed/Subwatershed:
Features ---> Rabbit track ---> Cross section ---> Flow direction ---> Hinge ---> Nail ---> Rock bar ---> Eroded bank ---> Undercut bank ---> Riparian vegetation ---> Lining tree ---> Fence ---> Culvert/Outlet ---> Steep embankment ---> Grasses ---> Tree ---> Stream log/tree ---> Woody debris ---> Station location ---> Vegetated Island		
Flow Type H1 Standing water H2 Current associated flow H3 Smooth surface flow H4 Appalling H5 Rippled H6 Unbroken standing wave H7 Broken standing wave H8 Chop H9 Flat fall		
Substrate S1 Silts S2 Sand S3 Gravel S4 Small cobble S5 Large cobble S6 Small boulder S7 Large boulder S8 Smooth S9 Irregular S10		
Other B1 Benchmark B2 Backsight B3 Downstream B4 Woody debris jam B5 VMC Valley neck contact B6 Bottom of slope B7 Top of slope B8 Erosion pit B9 Anvil B10 Upland B11 Terrace B12 Flood chute B13 Flood plain B14 Rock/park		
Additional Notes: p.1 Scale:		



Carruther's Creek, Pickering



General Site Characteristics

Project Code:


Date:	Aug 23, 2016	Stream/Reach:	Carruther's Creek
Weather:		Location:	Hollywood Cr, Pickering
Field Staff:	ER/LD/AM	Watershed/Subwatershed:	

Features	
	Reach break
	Cross-section
	Flow direction
	Riffle
	Pool
	Medial bar
	Eroded bank
	Undercut bank
	Rip rap/stabilization/gabion
	Leaning tree
	Fence
	Culvert/outfall
	Swamp/wetland
	Grasses
	Tree
	Instream log/tree
	Woody debris
	Station location
	Vegetated island

Flow Type	
H1	Standing water
H2	Scarcely perceptible flow
H3	Smooth surface flow
H4	Upwelling
H5	Rippled
H6	Unbroken standing wave
H7	Broken standing wave
H8	Chute
H9	Free fall

Substrate			
S1	Silt	S6	Small boulder
S2	Sand	S7	Large boulder
S3	Gravel	S8	Bimodal
S4	Small cobble	S9	Bedrock/till
S5	Large cobble		

Other			
BM	Benchmark	EP	Erosion pin
BS	Backsight	RB	Rebar
DS	Downstream	US	Upstream
WDJ	Woody debris jam	TR	Terrace
VWC	Valley wall contact	FC	Flood chute
BOS	Bottom of slope	FP	Flood plain
TOS	Top of slope	KP	Knick point



Carruther's Creek, Pickering

Range of Water Depths	0.42m-1m
Range of Velocities	Pool -0.009 m/s - 0.007 m/s
Undercutting	0.08m - 0.40m
Habitat Features	Rooted emergent
Riffle Substrate	Clay/silt, gravel, cobble, rootlets
Pool Substrate	Clay/silt, sand, rootlets
Bank Substrate	Clay/silt, rootlets
Riparian Vegetation	Major localized gaps, Canopy coverage: 60-79% shading
Large obstructions	6 beaver dams (1 breached)




Carruther's Creek, Pickering




- Electrofishing survey completed on September 15, 2016
- Base flow at approximately 2 lpm at time of survey
- Channel maturing with moderate riparian cover
- No riffles, very shallow slope and deep pools present
- Channel dominated with muck and submergent vegetation
- Riffle/pool sequence upstream of Highway 7
- Watercress present in pools
- Seven species of fish collected
- Seven Redside Dace captured during survey reach




Carruther's Creek, Pickering



- 230 electrofishing seconds
- 30 m reach
- Resident fish community dominated by Creek Chub
- Good pool depth but limited woody cover
- Channel lacks slope and suitable coarse sediment for Redside Dace spawning



Churchville Creek: Timberbank



General Site Characteristics		Project Code:	
Date:	Aug. 24, 2016	Stream/Reach:	Churchville Creek, Tr 1686
Weather:	30°C, sunny	Location:	Timberbank
Field Staff:	ER/AM	Watershed/Subwatershed:	

Features	Site Sketch:														
<ul style="list-style-type: none"> — — Reach break —x— Cross-section → Flow direction ~ Riffle ○ Pool ⊖ Medial bar ⊖ Eroded bank ⊖ Undercut bank ⊖ Rip rap/stabilization/gabion → Leaning tree —x— Fence ⊖ Culvert/outfall ⊖ Swamp/wetland ∨∨∨ Grasses ○ Tree ⊖ Instream log/tree ××× Woody debris ○ Station location ○ Vegetated island 	<p>Hand-drawn site sketch on grid paper showing a beaver pond circled in red. The sketch includes a north arrow, a legend for willow (K) and cattail (V), and various measurements such as WD=0.5m, WD=0.96m, WD=0.45m, WD=0.39m, WD=0.36m, WD=0.31m, and UC=0.15m. A dam is also indicated.</p>														
Flow Type <ul style="list-style-type: none"> H1 Standing water H2 Scarcely perceptible flow H3 Smooth surface flow H4 Upwelling H5 Rippled H6 Unbroken standing wave H7 Broken standing wave H8 Chute H9 Free fall 															
Substrate <table border="0"> <tr> <td>S1 Silt</td> <td>S6 Small boulder</td> </tr> <tr> <td>S2 Sand</td> <td>S7 Large boulder</td> </tr> <tr> <td>S3 Gravel</td> <td>S8 Bimodal</td> </tr> <tr> <td>S4 Small cobble</td> <td>S9 Bedrock/till</td> </tr> <tr> <td>S5 Large cobble</td> <td></td> </tr> </table>	S1 Silt	S6 Small boulder	S2 Sand	S7 Large boulder	S3 Gravel	S8 Bimodal	S4 Small cobble	S9 Bedrock/till	S5 Large cobble						
S1 Silt	S6 Small boulder														
S2 Sand	S7 Large boulder														
S3 Gravel	S8 Bimodal														
S4 Small cobble	S9 Bedrock/till														
S5 Large cobble															
Other <table border="0"> <tr> <td>BM Benchmark</td> <td>EP Erosion pin</td> </tr> <tr> <td>BS Backsight</td> <td>RB Rebar</td> </tr> <tr> <td>DS Downstream</td> <td>US Upstream</td> </tr> <tr> <td>WDJ Woody debris jam</td> <td>TR Terrace</td> </tr> <tr> <td>VWC Valley wall contact</td> <td>FC Flood chute</td> </tr> <tr> <td>BOS Bottom of slope</td> <td>FP Flood plain</td> </tr> <tr> <td>TOS Top of slope</td> <td>KP Knick point</td> </tr> </table>	BM Benchmark	EP Erosion pin	BS Backsight	RB Rebar	DS Downstream	US Upstream	WDJ Woody debris jam	TR Terrace	VWC Valley wall contact	FC Flood chute	BOS Bottom of slope	FP Flood plain	TOS Top of slope	KP Knick point	<p>Additional Notes:</p> <p>Scale:</p>
BM Benchmark	EP Erosion pin														
BS Backsight	RB Rebar														
DS Downstream	US Upstream														
WDJ Woody debris jam	TR Terrace														
VWC Valley wall contact	FC Flood chute														
BOS Bottom of slope	FP Flood plain														
TOS Top of slope	KP Knick point														

Churchville Creek: Timberbank

Range of Water depth	0.34m - 1.5m
Range of Velocities	Pool
	-0.006 m/s 0.044 m/s
Undercutting	0.15 m
Habitat Features	Rooted emergent/ submergent
Riffle Substrate	Clay/silt, gravel, cobble, rootlets
Pool Substrate	Clay/silt, sand, rootlets
Bank Substrate	Clay/silt, rootlets
Riparian Vegetation	Major localized gaps, Canopy coverage: >80 % shading
Large obstructions	2 Beaver dams (1 was 15m across)
Notes	Large amounts of flooding due to beaver dams



Churchville Creek, Timberbank




- Electrofishing survey completed on August 25, 2016
- Base flow at approximately 200 lpm at time of survey
- Channel maturing with dense riparian cover and dense woody cover in pools
- Riffles composed of cobbles, gravel and finer coarse sediment
- Beaver present with constructed dams
- Four species of fish collected
- Redside Dace captured 2.5 km downstream in 2009 by Stantec




Photo credit: Mark Pomeroy



Churchville Creek, Timberbank



- 480 electrofishing seconds
- 80 m reach
- Resident fish community dominated by Creek Chub
- Channel provides suitable habitat for all life stages of Redside Dace



Morningside Creek, Scarborough

Aerial photo taken:
16-08-30



General Site Characteristics

Project Code:

Date:	Aug 23, 2016	Stream/Reach:	Morningside Creek
Weather:		Location:	1/5 Seasons Drive
Field Staff:	TR/LD/JM	Watershed/Subwatershed:	

Features

	Reach break
	Cross-section
	Flow direction
	Riffle
	Pool
	Medial bar
	Eroded bank
	Undercut bank
	Rip rap/stabilization/gabion
	Leaning tree
	Fence
	Culvert/outfall
	Swamp/wetland
	Grasses
	Tree
	Instream log/tree
	Woody debris
	Station location
	Vegetated island

Flow Type

H1	Standing water
H2	Scarcely perceptible flow
H3	Smooth surface flow
H4	Upwelling
H5	Rippled
H6	Unbroken standing wave
H7	Broken standing wave
H8	Chute
H9	Free fall


Substrate

S1	Silt	S6	Small boulder
S2	Sand	S7	Large boulder
S3	Gravel	S8	Bimodal
S4	Small cobble	S9	Bedrock/till
S5	Large cobble		

Other

BM	Benchmark	EP	Erosion pin
BS	Backsight	RB	Rebar
DS	Downstream	US	Upstream
WDJ	Woody debris jam	TR	Terrace
VWC	Valley wall contact	FC	Flood chute
BOS	Bottom of slope	FP	Flood plain
TOS	Top of slope	KP	Knick point


Site Sketch:



Additional Notes:

Morningside Creek, Scarborough


Range of Water depth	0.55m- 1.10m
Range of Velocities	Riffle -0.009 m/s - 0.385 m/s
Undercutting	0.05m- 0.30m
Habitat Features	Rooted submergent
Riffle Substrate	Gravel, Cobble
Pool Substrate	Sand, gravel, parent
Bank Substrate	Clay/silt
Riparian Vegetation	Major localized gaps, Canopy coverage: <50 % shading
Large obstructions	Large amounts of flooding due to 5 Beaver dams
Notes	Flooded since 2013, fish observed




Morningside Tributary, Rouge River




- Electrofishing survey completed on September 15, 2016
- Base flow at approximately 20 lpm at time of survey
- Channel maturing with moderate riparian cover
- Riffles composed of cobbles and gravel
- Beaver present with constructed dams
- Nine species of fish collected
- Four Redside Dace captured during survey



Morningside Tributary, Rouge River



- 305 electrofishing seconds
- 30 m reach
- Resident fish community dominated by Creek Chub
- Channel lacks large woody debris in pools
- Plastic mesh in channel from original erosion blankets
- Culvert substrate oversized and limiting fish passage



Fletcher's Creek, Brampton

General Site Characteristics

Project Code:

Date:	Aug 24, 2016	Stream/Reach:	Fletcher's Creek
Weather:	30°C, sunny	Location:	Fletcher's Meadow
Field Staff:	AM/ER	Watershed/Subwatershed:	

Features

	Reach break
	Cross-section
	Flow direction
	Riffle
	Pool
	Medial bar
	Eroded bank
	Undercut bank
	Rip rap/stabilization/gabion
	Leaning tree
	Fence
	Culvert/outfall
	Swamp/wetland
	Grasses
	Tree
	Instream log/tree
	Woody debris
	Station location
	Vegetated island

Flow Type

H1	Standing water
H2	Scarcely perceptible flow
H3	Smooth surface flow
H4	Upwelling
H5	Rippled
H6	Unbroken standing wave
H7	Broken standing wave
H8	Chute
H9	Free fall


Substrate

S1	Silt	S6	Small boulder
S2	Sand	S7	Large boulder
S3	Gravel	S8	Bimodal
S4	Small cobble	S9	Bedrock/till
S5	Large cobble		


Other

BM	Benchmark	EP	Erosion pin
BS	Backsight	RB	Rebar
DS	Downstream	US	Upstream
WDJ	Woody debris jam	TR	Terrace
VWC	Valley wall contact	FC	Flood chute
BOS	Bottom of slope	FP	Flood plain
TOS	Top of slope	KP	Knick point

Site Sketch:



Additional Notes: Edenbrock Hill Dr.



Aerial photo:
16-08-29



Ministry of Natural Resources and Forestry

GEO

M O R P H I X

Fletcher's Creek, Brampton

Range of Water depth	0.55m- 1.10m
Range of Velocities	Pool -0.006 m/s - 0.044 m/s
Undercutting	0
Habitat Features	Rooted emergent
Riffle Substrate	Cobble
Pool Substrate	Clay/silt
Bank Substrate	Clay/silt
Riparian Vegetation	Major localized gaps, Canopy coverage: <50 % shading
Large obstructions	No beaver dams
Notes	Standing water, no flow



Fletcher's Creek, Credit River




- Electrofishing survey completed on August 25, 2016
- Base flow at approximately 40 lpm at time of survey
- Channel maturing with dense riparian cover with some large woody cover in pools
- Riffles composed of cobbles
- Channel dominated with muck
- Beaver present with constructed dams
- Six species of fish collected
- YOY Redside Dace captured in same survey reach in 2011 by Credit Valley Conservation




Photo credit: Brydon McVeigh

West Fletcher's Creek, Credit River




- 466 electrofishing seconds
- 100 m reach
- Resident fish community dominated by Creek Chub
- Channel lacks suitable coarse sediment for Redside Dace spawning



Conclusions

- Redside Dace will use constructed natural channels
- Corridors are providing for diverse and healthy fish communities
- In most of the channels reviewed, physical characteristics are still suitable for Redside Dace including morphology, substrate, wood debris, undercuts, and overhanging vegetation
- Surveys over the first 10 years showed relatively modest adjustments in substrate, cross sectional geometry
- In recent years significant changes in floodplain and channel characteristics where beavers have been present
- Pools > 1 m depth even during low flow conditions in systems that would otherwise have been considered seasonal habitat
- Increased overwintering potential for Redside Dace





Lessons Learned

- Even channels that have been stable for more than a decade can show rapid changes due to the influence of external disturbances, such as beavers
- Beavers may occupy the systems when vegetation reaches a certain size – all the channels were a similar age and relied heavily of pioneering plant species – this could explain the recent changes across the corridors
- The current overwintering potential, floodplain connectivity and morphological variability were likely not anticipated by the designers – this is a good thing
- Important to recognize that the corridors we install can mature into overwintering habitat for Redside dace, moving forward
- Goes to show how unpredicted natural events like the presence of beaver activity can shape a channel
- Issue with oversized riffle substrates at Fletchers' illustrating that designers and agency reviewers need to be cautious in balancing erosion/instability concerns with the finer substrate needs of riffle spawning species

Thanks to Margaret Berube, Liz Miller, Jason Krompart,
Emily Rick, Alex Meeker, and Lindsay Davis



THANK YOU...